


## Machine plan



	L1	L2	L3	L4	L5	L6	B1	B2	B3	B4	H1	H2	H3
SF 26 S-Dnt	6742	2085	3023	4013	1500	-	1624	1170	1333	-	1830	1730	2210
SF 32 S-Dnt	7014	2535	2850	4063	1500	-	1833	1500	1564	-	2030	1930	2216
SF 51 S-Dnt	7087	2815	2645	4040,45	1500	-	2039	1500	1585	-	2190	2035	2450
SFH 160 S-Dnt	-	2815	-	-	1500	750	2039	1500	1585	2000	2190	2035	2450
AF 32 S-Dnt	7087	2815	2645	4026,5	1500	-	2039	1500	1585	-	2190	2035	2450
AFH 130 S-Dnt	-	2815	-	-	1500	750	2039	1500	1585	2000	2190	2035	2450